



Muswellbrook Coal Company Limited

Spontaneous Combustion Report

For: Environmental Protection Licence 656

Reporting Period: January 2020

Authority Holder: Muswellbrook Coal Company Limited

Report Date: 29 April 2020

**Approved by: Julie Thomas
Environmental Superintendent**



Table of Contents

1.0 INTRODUCTION.....	1
2.0 SPONTANEOUS COMBUSTION MANAGEMENT MEASURES.....	1
3.0 GAS MONITORING RESULTS	3
4.0 RESPONSE TO ELEVATED GAS LEVELS.....	11
5.0 CORRELATION BETWEEN MANAGEMENT ACTIVITIES AND GAS LEVELS	11
6.0 CORRELATION BETWEEN COMMUNITY COMPLAINTS AND GAS LEVELS	11

List of Tables

Table 1: Spontaneous Combustion Management Measures.....	1
Table 2: Classification of Spontaneous Combustion Outbreaks	2
Table 3: Summary of Spontaneous Combustion	3
Table 4: Data Capture Rates.....	3
Table 5: Actions Taken in Response to Elevated Gas Levels.....	11

List of Figures

Figure 1: Location of Spontaneous Combustion Outbreaks in Open Cut 1.....	4
Figure 2: Location of Spontaneous Combustion Outbreaks in Open Cut 2.....	5
Figure 3: Hydrogen Sulphide 30 Minute Results	6
Figure 4: Sulphur Dioxide 1 Hour Results	7
Figure 5: Hydrogen Sulphide 1 Hour Results	8
Figure 6: Sulphur Dioxide 24 Hour Results	9
Figure 7: Hydrogen Sulphide 24 Hour Results	10

1.0 INTRODUCTION

The coal seams mined by the Muswellbrook Coal Company (MCC) operations are the Greta Coal Measures. These measures have a history of spontaneous combustion. Spontaneous combustion has been a long-term issue at MCC since the first operation commenced in 1907.

A Spontaneous Combustion Management Plan (SCMP) has been prepared according to the specific requirements of the Development Consent. The main objective of the SCMP is to minimise the occurrence of spontaneous combustion and manage the effect by identification, control, removal, mitigation and prevention in the following areas:

- Existing open cut and underground workings;
- Drilling and blasting;
- Mining of overburden;
- Mining of coal;
- Emplacement of overburden;
- Emplacement of washery reject; and
- Coal stockpiles.

The Environment Protection Authority (EPA) require MCC to provide reports on spontaneous combustion management and monitoring on a monthly basis. This report identifies:

- Spontaneous combustion management during the reporting period;
- Gas monitoring results;
- Number of complaints relating to spontaneous combustion;
- Response to hydrogen sulphide levels above the odour threshold; and
- Correlation between spontaneous combustion on site with gas results and complaints received.

2.0 SPONTANEOUS COMBUSTION MANAGEMENT MEASURES

The daily spontaneous combustion management measures for the reporting period are shown in **Table 1**.

Table 1: Spontaneous Combustion Management Measures

Date	Water Sprays	Water Carts Assisting	Capping	Hot Material Removal	Comments
01/01/20	S21	OC1	S21	-	
02/01/20	S21	S21	S21	-	
03/01/20	S21	S21	S21	-	
04/01/20	S21	OC1	S21	S21	
05/01/20	S21	OC1	S21	S21	
06/01/20	-	OC1	S21	-	
07/01/20	-	S21	S21	-	
08/01/20	-	S21	S21	-	
09/01/20	-	S21	S21	-	



Date	Water Sprays	Water Carts Assisting	Capping	Hot Material Removal	Comments
10/01/20	-	OC1	S21	-	
11/01/20	-	OC1	S21	-	
12/01/20	-	OC1	RL137	-	
13/01/20	-	S22	S21	-	
14/01/20	-	S21	S21	-	
15/01/20	-	S21	S21	-	
16/01/20	-	OC1	S21	S22	
17/01/20	-	S22	S21	S22	
18/01/20	-	S21	S21	-	
19/01/20	-	S21	S21	S22	
20/01/20	-	S22	S21	S22	
21/01/20	-	S22	S21	S22	
22/01/20	-	S22	S21	-	
23/01/20	-	S22	S21	-	
24/01/20	-	OC1	S21	-	
25/01/20	-	OC1	-	-	
26/01/20	-	OC1	-	-	
27/01/20	-	OC1	S21	-	
28/01/20	-	S22	S21	-	
29/01/20	-	OC1	S21	-	Installing pipe for water infusion
30/01/20	-	OC1	-	-	Clay seal finished in S21
31/01/20	-	S22	S21	S22	

The classification system for spontaneous combustion outbreaks is provided in **Table 2**. A summary of the areas affected by spontaneous combustion and the areas controlled and treated during the reporting period is provided in **Table 3**. The locations of these areas can be seen in **Figure 1** and **Figure 2**.

Table 2: Classification of Spontaneous Combustion Outbreaks

Classification	Description
A	Open flame
B	Visible steam or smoke
C	Other physical evidence of spontaneous combustion (e.g. cracks, coal tars, sulphur crusting, etc)

* - classification revised in November 2019

Table 3: Summary of Spontaneous Combustion

Site Map Location	Classification (A-C)	Affected Area Without Active Control (m ²)	Active Controls Completed	Area Controlled (m ²)
Open Cut 1	A	20*	Mining Capping Infusion	12**
	B	22*		35**
Open Cut 2	N/A	0*	None Required	5,100**
SUMMARY				
Total Area Affected		42*		
Total Area Controlled		47**		

* - at end of reporting period

** - during reporting period

No spontaneous combustion outbreaks were observed in Open Cut 2 throughout January 2020. Therefore, no active controls were implemented in Open Cut 2.

3.0 GAS MONITORING RESULTS

The gas monitoring results are displayed graphically in **Figure 3** to **Figure 7**. As noted in these graphs, there were no results above the health impact assessment criteria or the odour threshold during the reporting period.

The data capture rates for the reporting period and the last 12 months are shown in **Table 4**.

Table 4: Data Capture Rates

Monitoring Location	Pollutant	Averaging Period	Data Capture – January (%)	Data Capture – 12 Month Rolling (%)
Point 9, Nisbet	Hydrogen Sulphide	30 minutes	96.2	95.9
		1 hour	94.6	94.3
		24 hours	96.8	98.1
Point 10, Muscle Creek	Hydrogen Sulphide	30 minutes	95.2	95.7
		1 hour	93.5	93.9
		24 hours	96.8	98.4
Point 15, Nisbet	Sulphur Dioxide	1 hour	94.5	94.4
		24 hours	96.8	98.1
Point 16, Muscle Creek	Sulphur Dioxide	1 hour	94.0	94.1
		24 hours	96.8	98.4




Figure 1: Location of Spontaneous Combustion Outbreaks in Open Cut 1




Figure 2: Location of Spontaneous Combustion Outbreaks in Open Cut 2




Figure 3: Hydrogen Sulphide 30 Minute Results




Figure 4: Sulphur Dioxide 1 Hour Results




Figure 5: Hydrogen Sulphide 1 Hour Results




Figure 6: Sulphur Dioxide 24 Hour Results




Figure 7: Hydrogen Sulphide 24 Hour Results

4.0 RESPONSE TO ELEVATED GAS LEVELS

When MCC receive an alarm that the hydrogen sulphide levels at the gas monitors are above the odour threshold of 8ppb, a review of operations and gas sources in the local area is undertaken. The responses to any alarms received during the reporting period are shown in Table 5.

Table 5: Actions Taken in Response to Elevated Gas Levels

Date and Time of Alarm	Location of Alarm	Weather Conditions at Time of Alarm	Response to Alarm	Classification of Spontaneous Combustion
No alarms were received during the reporting period				

5.0 CORRELATION BETWEEN MANAGEMENT ACTIVITIES AND GAS LEVELS

A review of the correlation between spontaneous combustion management activities, gas levels and complaints has been undertaken. This review has found that spontaneous combustion management activities were occurring throughout the reporting period and gas levels during the reporting period were low.

6.0 CORRELATION BETWEEN COMMUNITY COMPLAINTS AND GAS LEVELS

There were no complaints received during the reporting period related to odour or visual impacts from spontaneous combustion.