



February 2025 Blast Monitor Summary			Location			
			Goonbri East		Wilberoi East	
Blast ID	Date	Time	Overpressure	Vibration	Overpressure	Vibration
			dB(L)	mm/s	dB(L)	mm/s
C_BR33_29	4/02/2025	2:56:07 PM	95.00	0.25	96.60	0.10
C_MN32_12	8/02/2025	2:56:07 PM	91.00	0.16	96.60	0.13
C_BC17_30	19/02/2025	1:04:00PM	94.40	0.95	92.40	0.27
E_MN25_03	19/02/2025	3:15:00PM	99.60	0.28	92.60	0.09
C_MN32_05	25/02/2025	3:15:00PM	96.00	0.34	94.90	0.34
C_BC21_26	27/02/2025	3:07:18 PM	93.90	0.22	92.40	0.18
C_TS39_29	28/02/2025	3:07:18 PM	104.00	0.12	94.60	0.09
EPL 12407 Criteria			<120 dB(L)	<10 mm/s		

A second blast was required to take place on February 19 due to a misfire caused by a technical fault.