

<b>Boggabri Coal - Wilberoi East monitor</b>			
<b>Date</b>	<b>Estimated Mining Leq 15 min Day</b>	<b>Estimated Mining Leq 15 min Evening</b>	<b>Estimated Mining Leq 15 min Night</b>
	<b>7:15- 18:00</b>	<b>18:15- 22:00</b>	<b>22:15- 7:00</b>
1/06/2023	23.1	19.6	24.7
2/06/2023	26.6	19.9	25.5
3/06/2023	23.4	19.9	27.4
4/06/2023	32.0	27.9	30.3
5/06/2023	30.5	27.6	28.8
6/06/2023	27.5	20.4	28.0
7/06/2023	24.5	20.4	24.6
8/06/2023	29.7	19.5	20.9
9/06/2023	20.4	19.9	22.1
10/06/2023	22.0	20.6	27.9
11/06/2023	23.2	21.9	27.8
12/06/2023	25.6	22.2	26.5
13/06/2023	27.3	24.8	22.4
14/06/2023	24.3	20.1	21.5
15/06/2023	23.5	21.1	22.2
16/06/2023	25.0	21.2	30.4
17/06/2023	25.8	20.0	26.7
18/06/2023	27.5	20.6	24.0
19/06/2023	23.3	20.5	20.8
20/06/2023	22.5	19.4	28.1
21/06/2023	28.5	32.3	31.9
22/06/2023	33.2	27.6	27.7
23/06/2023	27.7	22.5	22.8
24/06/2023	27.7	25.6	26.0
25/06/2023	33.7	21.6	21.6
26/06/2023	25.1	22.4	23.3
27/06/2023	24.9	21.3	25.2
28/06/2023	31.8	23.5	20.7
29/06/2023	24.2	21.4	19.1
30/06/2023	NR	NR	NR

NR 30/6/23 due to noise meter reading 0.0. Field technician investigated site 3/7/23 to find noise meter was off. Field technician restarted 3/7/2023.