



September 2021 Blast Monitor Summary			Location			
			Goonbri East		Wilberoi East	
Blast ID	Date	Time	Overpressure	Vibration	Overpressure	Vibration
			dB(L)	mm/s	dB(L)	mm/s
C_TS32_25B	4/09/2021	3:02PM	82.1	0.08	106.1	<0.2
C_MN22_06	4/09/2021	3:04PM	96.1	0.12	102.8	0.21
C_TS31_33_TRIM	8/09/2021	3:39pm	85.6	0.08	85.3	0.21
C_BC23_22	8/09/2021	3:41pm	101.6	0.17	93.2	0.23
C_MN22_07	10/09/2021	3:32PM	90	0.13	88.8	0.23
C_MN23_13	14/09/2021	3:28PM	98.3	0.07	97.3	0.25
C_BC24_17	14/09/2021	3:30PM	101.2	0.13	103.9	0.24
C_TS32_31	16/09/2021	3:28PM	96.9	0.12	94.8	0.21
E_MN08_05	18/09/2021	3:32PM	100.1	0.35	93.2	0.26
E_BR17_06_PS	18/09/2021	3:32PM	100.1	0.35	93.2	0.26
E_BR12_03	20/09/2021	11:01AM	88.1	0.08	99.3	0.22
C_BC24_22	22/09/2021	3:33pm	96.9	0.15	88.8	0.23
C_MN20_21_TRIM	22/09/2021	3:33pm	96.9	0.15	88.8	0.23
E_MN08_06	24/09/2021	3:45pm	98.3	0.11	96.2	<0.2
C_BR31_18	24/09/2021	3:45pm	98.3	0.11	96.2	<0.2
E_BR17_06_TRIM	27/09/2021	3:35pm	96.9	0.27	96.9	0.27
C_TS33_30_350RL	27/09/2021	3:36pm	96.9	0.27	96.9	0.27
			<120 dB(L)	<10 mm/s		
EPL 12407 Criteria						