



| October 2021 Blast Monitor Summary | | | Location | | | |
|---------------------------------------|------------|-------------|--------------|-----------|---------------|-----------|
| | | | Goonbri East | | Wilberoi East | |
| Blast ID | Date | Time | Overpressure | Vibration | Overpressure | Vibration |
| | | | dB(L) | mm/s | dB(L) | mm/s |
| C MN16 25 | 5/10/2021 | 11:06:00 AM | 100.1 | 0.25 | 100.1 | 0.23 |
| C JE24 14 | 8/10/2021 | 3:40:00 PM | 96.1 | <0.2 | 93.2 | 0.21 |
| C BR33 05 | 9/10/2021 | 3:29:00 PM | 91.6 | <0.2 | 100.1 | 0.26 |
| C THO31 33 TRIM | 18/10/2021 | 3:34:00 PM | 96.9 | 0.42 | 96.2 | 0.28 |
| C MN18 25 | 18/10/2021 | 3:34:00 PM | 96.9 | 0.42 | 96.2 | 0.28 |
| C BC22 24 | 22/10/2021 | 3:36:00 PM | 103.3 | 0.2 | 96.2 | 0.26 |
| C BR17 05 BR13 PS | 22/10/2021 | 3:36:00 PM | 103.3 | 0.2 | 96.2 | 0.26 |
| C MN21 20 | 25/10/2021 | 3:41:00 PM | 102.9 | 0.11 | 94.8 | 0.24 |
| C BR34 05 | 27/10/2021 | 3:38:00 PM | 93 | 0.12 | 102.8 | 0.26 |
| | | | <120 dB(L) | <10 mm/s | | |
| EPL 12407 Criteria | | | | | | |