



| December 2021 Blast Monitor Summary | | | Location | | | |
|--|------------|------------|--------------|-----------|---------------|-----------|
| | | | Goonbri East | | Wilberoi East | |
| Blast ID | Date | Time | Overpressure | Vibration | Overpressure | Vibration |
| | | | dB(L) | mm/s | dB(L) | mm/s |
| C_MN23_05 | 3/12/2021 | 3:05PM | 96.1 | 0.13 | 94.8 | 0.2 |
| E_BC10_05 | 6/12/2021 | 2:45:00 PM | 96.9 | 0.37 | 91.3 | 0.22 |
| C_THO32_33 | 14/12/2021 | 3:02:00 PM | 87.2 | 0.06 | 100.5 | 0.03 |
| C_TS34_33_RL350 | 17/12/2021 | 3:01:00 PM | 84.7 | 0.53 | 91.3 | 0.14 |
| C_JE23_19 | 21/12/2021 | 3:14PM | 101.1 | 0.13 | 91.6 | 0.15 |
| C_MN23_07 | 21/12/2021 | 3:14PM | 101.1 | 0.13 | 91.6 | 0.15 |
| E_BC11_05 | 22/12/2021 | 4:01PM | 88.9 | 0.33 | 91..0 | 0.05 |
| C_JE23_20 | 31/12/2021 | 11:37AM | 96.1 | 0.11 | 84.7 | 0.46 |
| E_BR17_05_BR22 | 31/12/2021 | 11:37AM | 96.1 | 0.11 | 84.7 | 0.46 |
| EPL 12407 Criteria | | | <120 dB(L) | <10 mm/s | | |