



| March 2021<br>Blast Monitor Summary |            |         | Location     |           |                       |           |
|-------------------------------------|------------|---------|--------------|-----------|-----------------------|-----------|
|                                     |            |         | Goonbri East |           | Wilberoi East         |           |
| Blast ID                            | Date       | Time    | Overpressure | Vibration | Overpressure          | Vibration |
|                                     |            |         | dB(L)        | mm/s      | dB(L)                 | mm/s      |
| C_BC21_25                           | 2/03/2021  | 3:01pm  | 111.6        | 0.14      | 94.8                  | 0.23      |
| C_TS32_31                           | 5/03/2021  | 4:59pm  | 88.1         | 0.1       | 88.8                  | 0.12      |
| C_BC21_18                           | 5/03/2021  | 5:01pm  | 104          | 0.24      | 101.5                 | 0.36      |
| C_BC21_25_TRIM                      | 9/03/2021  | 11:05am | 100.1        | 0.26      | 110.6                 | 0.22      |
| C_BC23_15                           | 16/03/2021 | 3:05pm  | 90           | 0.08      | 103.3                 | 0.09      |
| C_MN16_05                           | 16/03/2021 | 3:07pm  | 82.1         | 0.14      | 103.9                 | 0.17      |
| C_JE20_20                           | 23/03/2021 | 10:48am | 106.9        | 0.11      | 100.8                 | 0.09      |
| E_BC08_05                           | 26/03/2021 | 3:04PM  | 95.1         | 0.35      | 98.3                  | 0.15      |
| E_BR12_02_TRIM                      | 31/03/2021 | 4:42pm  | 94.1         | 0.14      | 100.7                 | 0.09      |
| EPL 12407 Criteria                  |            |         | <120 dB(L)   | <10 mm/s  | *BT - Below Threshold |           |